



Pacific Asian Enterprises, Inc.  
 PO Box 874 • Dana Point, CA 92629  
 (949) 496-4848 phone (949) 240-2398 fax

## Nordhavn 47#58

Date: 01.08.10

	DESCRIPTION	PRICE
	230v 50Hz - 24v Boat	
	CE Mark Compliance	
	<b>BASE PRICE</b>	\$915,824.00
	<b>LAYOUT OF N47 # 58</b>	
1	Flybridge, including Todd helm chair, fixed fiberglass seating, cushions, engine room controls, bow thruster and windlass remote - hatch is included.	\$34,374.00
<b>A</b>	<b>EXTERIOR GEL COAT COLORS</b>	
1	Hull: Arocoat #340 Grey or 'Supershield' white	Included
2	Non-skid: Lt. Grey or Beige	Included
3	Stripe: Arocoat #348 Dk. Blue (std)	Included
4	Bottom Paint: Petite Trinidad Black	
<b>B</b>	<b>MACHINERY &amp; ENGINE ROOM DETAILS</b>	
1	12 KW Northern Lights Generator with sound enclosure and gen sep muffler. 240v/24v - 50Hz (model # M843NW2)	\$24,840.00
2	Air Conditioning - (240v - 50Hz) Marine Air - reverse cycle with digital controls - 2X12,000 (VTD 12K) btu for saloon, 1X16,000 (VTD 16K) btu for wheelhouse, 2X10,000 (VTD 10K) btu for staterooms -- Total of 60,000 btus	\$34,252.00
3	Lugger L844D 40 hp wing engine with separate 10 gallon day tank - 24v start and Gori prop. 2 x Lifeline 4D batteries shared with gen set	\$27,338.00
4	Side power 24v 10.7 HP Bow Thruster includes: model #SP155TC thruster, 9.8" I.D. tunnel, 1 x #SM896 joy stick control station, #SM897524 automatic main switch/fuse holder, 400 amp fuse	\$11,611.00
5	American Bow Thruster (TRAC) 220 stabilizing system. Keel cooled	\$45,184.00
6	Fire suppression system in lazarette. Pull cable and alarm (FD-350M)	\$1,540.00
7	PAE supplied Reverso oil change system - hard plumbed into the main engine, generator and wing engine.	\$1,506.00
8	Lightning ground system with copper plate on hull - #2 wire to base of mast and Forespar wand	\$1,040.00
9	SSB ground plane to include dynaplate and 3" copper ribbon from dynaplate (using Guest #4018 dynaplate) over washer/dryer	\$1,401.00
10	1 x additional propane bottle (total 3)	\$387.00
11	Install a temperature sensor in the engine room with a temperature display in the wheelhouse.	\$415.00
<b>C</b>	<b>PLUMBING SYSTEM</b>	
1	Salt water deck washdown bow and stern - including spigot, intake thruhull, strainer and Shurflo Problaster water pump	\$1,099.00
2	Fresh water wash down bow, stern and engine room. Uses house fresh water pump	\$646.00
3	Fresh water spigot added to the stack base on the boat deck.	\$231.00
4	Watermaker installation at factory - Village Marine Squirt 600 220v - 50Hz with auto back flush	\$13,829.00
5	Scandvik cockpit shower h/c - #10640	\$624.00
6	Add "Y" valve at galley sink.	\$452.00
7	Install a second backup fresh water pump	\$916.00
<b>D</b>	<b>LIGHTING</b>	



Pacific Asian Enterprises, Inc.  
 PO Box 874 • Dana Point, CA 92629  
 (949) 496-4848 phone (949) 240-2398 fax

## Nordhavn 47#58

Date: 01.08.10

		DESCRIPTION	PRICE
	1	Guest 'Beamer' remote spotlight - with controls in wheelhouse and flybridge	\$1,112.00
	2	2 x Ritchie compass FN-201 4.5" card - does not include swinging compass. 1 in the PH and 1 on the FB	\$1,110.00
<b>E</b>		<b>ELECTRICAL SYSTEM</b>	
	1	2 x extra 8D batteries for house system, for a total of 6	\$2,195.00
	2	12v outlet in pilothouse	\$145.00
	3	Install a Victron " Centaur Battery Charger" 24V100A 50/60hz	\$1,420.00
	4	Maricom supply and installation of Furuno electronics package Invoice #3017 Incoive #15593	\$25,185.00
<b>F</b>		<b>INTERIOR NOTES</b>	
	1	Ultraleather upholstery (salon settees, wheelhouse settee, stool in GSR) Ultraleather #291-3700 "Ivory"	\$2,080.00
	2	Teak & Spruce flooring throughout	NC
	3	Salon table to have starburst pattern	\$405.00
	1	<b>GALLEY</b>	
	a.	Sliding locker door above stove in galley (3 doors plus spice rack)	\$809.00
	b.	Granite in galley to be #11	NC
	2	<b>SALON</b>	
	a.	Install 2 x 24v Hella fans in the salon	\$305.00
	3	<b>HEADS</b>	
	a.	Granite in heads to be #14	NC
	4	<b>PILOTHOUSE</b>	
	a.	Bunk behind wheelhouse settee covered with Ultraleather #291-3700 "Ivory"	\$308.00
	b.	Maytag/Asko washer/dryer - 50Hz ILO standard (MAF9501AEW/MDE9601AEW)	\$2,694.00
	c.	Stidd 500N-2x2 Low back " Slimline" Admiral helm chair, Med. Pedestal, 'Ultraleather '#291-3700 "Ivory", powdercoated hardware.	\$6,318.00
	d.	Install 2 x 24v Hella fans in the pilothouse	\$305.00
<b>G</b>		<b>EXTERIOR AND DECK HARDWARE</b>	
	1	Paravane Stabilizer system complete	\$16,935.00
	2	121lb Rocna Anchor	\$1,535.00
	3	400 feet - 3/8" HT chain	\$2,268.00
	4	Marinco 50a 125/250v 50' shore power cord	\$693.00
	5	Spurs line cutter on main prop shaft	\$1,156.00
	6	Bow tow eye ring - 12" above water line	\$405.00
	7	Chain stopper for 3/8" chain	\$804.00



Pacific Asian Enterprises, Inc.  
 PO Box 874 • Dana Point, CA 92629  
 (949) 496-4848 phone (949) 240-2398 fax

## Nordhavn 47#58

Date: 01.08.10

	DESCRIPTION	PRICE
8	Additional Todd helmchair on flybridge	\$673.00
9	Install a chain counter with a display in the PH and on the FB	\$1,025.00
10	6 x Salon window storm plates	\$918.00
11	Install a cockpit bbq console. Console to include a LPG bbq, sink and faucet.	\$7,219.00
12	2 x fishing rod holders. Exact location TBD	\$390.00
13	Install a folding bimini on the FB with a canvas top. Canvas color to match boot stripe	\$5,650.00
14	FB to have a destroyer type wheel	NC
15	Add propspeed to all underwater metal parts except for the keel cooler	\$1,500.00
16	Add Oceanair screen/shades on all deck hatches	\$1,345.00
17	Sea wolf canvas to provide external P/H window covers & exterior hatch covers - color of canvas to be white	\$1,725.00
18	Sea wolf canvas to provide external salon window covers. 6 x salon side windows port & stbd, 2 x aft salon windows port & stbd and 1 x aft salon door window. Color to be white.	\$785.00
19	Add Besezoni gangway IMTRA PT163.25 BZ82001032 - 98" (2.5m) install deck socket on the top of the aft deck cap-rail. Price to include storage under dingy.	\$3,846.00
20	Add one FX -55 anchor with built in storage located in the lazarette. Exact location TBD.	\$870.00
21	Please provide and ship to the factory for installation a Sportmaster 1101 deluxe hypalon white dingy, MFS 18 EPS Tohatsu outboard, white sunbrella cover, spare parts for engine and (4) 21" Weaver chocks. Price includes installation.	\$15,713.00
<b>H</b>	<b>HANDRAILS</b>	
1	Handrail overhead at stairs from Portuguese bridge to lower deck.	\$337.00
2	18" hand rail on overhead down stairs from pilot house to salon - this should be placed 3" up from salon overhead height	\$337.00
3	Stbd side from boarding door forward and curved up rise in bullworks - from boarding door to 18" short of teak cap rail on aft deck.	\$1,177.00
4	Add curved SS handrail to caprail - above sheerbreak, adjacent to steps from PH to main deck walkway	\$360.00
5	L' shaped hand rails on the port and stbd stern quarters	\$924.00
6	Handrail in cockpit, portside from teak caprail to port side salon wall	\$360.00
7	Handrail on portuguese bridge from foredeck door to port side of railing.	\$1,499.00
8	Handrail above standard Sub Zero freezer in stairway leading from pilothouse to cabins.	\$276.00
9	Handrail overhead at end of stairway leading from pilot house to cabins	\$276.00
	<b>Total</b>	<b>\$1,232,901</b>